

**Spot Source Water Supply Schemes (Hand Pumps, STC, Wells etc.) Status as on 31-3-2005 Division:- Investigation
Division,Shillong**

Division	Sub-Division	Sl.No	Name of		Name of	Number	Functionin g		Reasons	Date on	
			Scheme		villages/ habitations covered	of spot sources installed/ constructed	Numbers Functionin g	Numbers Non Functioning	for Non functioning	which it will be made fully functional	Remarks
1	2	3	4		6	7	8	9	10	11	12
Investigation	Mechanical	1	Mawtawar	HP	Mawtawar	1	1	0			
Investigation	Mechanical	2	Mawiong D.T.W.W.S.S.	HP	Mawiong	1		1	NF7	Cannot be made functioned	Alternative piped w.s.s. taken up
Investigation	Mechanical	3	Rangbihbih D.T.W. W..S.S.	HP	Rangbihbih	2	2	0			
Investigation	Mechanical	4	Umsaw D.T.W.W.S.S.	HP	Umsaw	5	5	0	-		
Investigation	Mechanical	5	Nongsawing D.T.W. W.S.S.	HP	Nongsawing	2	2	0	-	-	-
Investigation	Mechanical	6	Pomkaniew D.T.W. W.S.S.	HP	Pomkaniew	1	1	0	-	-	
Investigation	Mechanical	7	12th Mile D.T.W. W.S.S.	HP	12th Mile	1	1	0			
Investigation	Mechanical	8	Umtyngar D.T.W. W.S.S.	HP	Umtyngar	1	1	0			
Investigation	Mechanical	9	Maweitnai D.T.W. W.S.S.	HP	Maweitnai	2	2	0			
Investigation	Mechanical	10	Mawan D.T.W. W.S.S.	HP	Mawan	2	2	0			
Investigation	Mechanical	11	Nongrim Hills,Nong- shilliang D.T.W. W.S.S.	HP	Nongrim Hills, Nongshilliang	8	8	0			
Investigation	Mechanical	12	Nongrim Hills,Nong- shillaing DT.W. W.S.S.	HP	Nongrim Hills, Nongshilliang	7	7	0			
Investigation	Mechanical	13	Rynjah D.T.W. W.S.S.	HP	Rynjah	1	0	1	NF4	Cannot be made functioned	Alternative piped w.s.s. taken up
Investigation	Mechanical	14	Umralleng D.T.W.W.S.S	HP	Umralleng	1	1	0			
Investigation	Mechanical	15	RangKyrshie D.T.W. W.S.S.	HP	Rangkyrshe	4	4	0			

1	2	3	4		6	7	8	9	10	11	12
Investigation	Mechanical	16	Mawlai Umshing D.T.W. W.S.S.	HP	Mawlai Umshing	1	1	0			
Investigation	Mechanical	17	Rohpadai D.T.W. W.S.S.	HP	Rohpadai	1	1	0			
Investigation	Mechanical	18	Auxillium School	HP	Auxillium School	2	2	0			
Investigation	Mechanical	19	Mawnariang D.T.W. W.S.S.	HP	Mawnariang	1	1	0			
Investigation	Mechanical	20	Mawkhar D.T.W. W.S.S.	HP	Mawkhar	4	4	0			
Investigation	Mechanical	21	Itshyrwat D.T.W.W.S.S	HP	Itshyrwat	1	1	0			
Investigation	Mechanical	22	Mawlong D.T.W.W.S.S.	HP	Mawlong	1	1	0			
Investigation	Mechanical	23	Umrynjah D.T.W.W.S.S	HP	Umrynjah	2	2	0			
Investigation	Mechanical	24	Nongkohlew D.T.W. W.S.S.	HP	Nongkohlew	1	1	0			
Investigation	Mechanical	25	Mawsiatkhnem D.T.W. W.S.S	HP	Mawsiatkhnem	4	4	0			
Investigation	Mechanical	26	Mynsain D.T.W.W.S.S.	HP	Mynsain	3	3	0			
Investigation	Mechanical	27	Pomsynteng D.T.W. W.S.S.	HP	Pomsynteng	4	4	0			
Investigation	Mechanical	28	Pdengshnong D.T.W. W.S.S.	HP	Pdengshnong	6	6	0			
Investigation	Mechanical	29	Umsaw D.T.W.W.S.S.	HP	Umsaw	4	4	0			
Investigation	Mechanical	30	Mynsain D.T.W.W.S.S.	HP	Mynsain	4	4	0			
Investigation	Mechanical	31	Pdengshnong D.T.W. W.S.S.	HP	Pdengshnong	4	4	0			
Investigation	Mechanical	32	Pomsynteng D.T.W. W.S.S.	HP	Pomsynteng	4	4	0			
Investigation	Mechanical	33	Rohpadai D.T.W.W.S.S	HP	Rohpdai	4	4	0			
Investigation	Mechanical	34	Mawkhar D.T.W.W.S.S.	HP	Mawkhar	4	4	0			
Investigation	Mechanical	35	Rangkyrshe D.T.W. W.S.S.	HP	Rangkyrshe	4	4	0			
Investigation	Mechanical	36	Mawsiatkhnem D.T.W. W.S.S.	HP	Mawsiatkhnem	3	3	0			
Investigation	Mechanical	37	Itshyrwat D.T.W.W.S.S	HP	Itshyrwat	2	2	0			
Investigation	Mechanical	38	Mawpun D.T.W. W.S.S.	HP	Mawpun	2	2	0			
Investigation	Mechanical	39	Nongkohlew D.T.W. W.S.S.	HP	Nongkohlew	3	3	0			

1	2	3	4		6	7	8	9	10	11	12
Investigation	Mechanical	40	Umrynjah D.T.W. W.S.S.	HP	Umrynjah	2	2	0			
Investigation	Mechanical	41	Laitlum D.T.W. W.S.S.	HP	Laitlum	1	1	0			
Investigation	Mechanical	42	Laitdiengsai D.T.W. W.S.S.	HP	Laitdiengsai	1	1	0			
Investigation	Mechanical	43	Mawiapbang D.T.W. W.S.S.	HP	Mawiapbang	1	0	1	NF4	Cannot be made functioned	Alternative piped w.s.s taken up
Investigation	Mechanical	44	Upper Jongksha D.T.W.W.S.S.	HP	Upper Jongksha	3	3	0			
Investigation	Mechanical	45	Mynsang D.T.W.W.S.S	HP	Mynsang	2	2	0			
Investigation	Mechanical	46	Jatshlakadong D.T.W. W.S.S.	HP	Jatshlakadong	2	2	0			
Investigation	Mechanical	47	Jatshshnonglyer D.T.W. W.S.S.	HP	Jatshnonglyer	2	2	0			
Investigation	Mechanical	48	Laitkyrshong D.T.W. W.S.S.	HP	Laitkyrshong	3	3	0			
Investigation	Mechanical	49	Umkhoi D.T.W.W.S.S	HP	Umkhoi	1	1	0			
Investigation	Mechanical	50	Pashong D.T.W.W.S.S	HP	Pashong	1	1	0			
Investigation	Mechanical	51	Mawlong D.T.W.W.S.S.	HP	Mawlong	1	1	0			
Investigation	Mechanical	52	Wahlyngkien D.T.W. W.S.S.	HP	Wahlynkien	1	1	0			
Investigation	Mechanical	53	Kyriem D.T.W. W.S.S.	HP	Kyriem	1	1	0			
Investigation	Mechanical	54	Nongkwai D.T.W.W.S.S	HP	Nongkwai	1	1	0			
Investigation	Mechanical	55	Phanniewblah D.T.W. W.S.S.	HP	Phanniewblah	3	3	0			
Investigation	Mechanical	56	Mawlum D.T.W.W.S.S	HP	Mawlum	2	2	0			
Investigation	Mechanical	57	Umryniut D.T.W.W.S.S.	HP	Umryniut	1	1	0			
Investigation	Mechanical	58	Mawmyrsiang D.T.W. W.S.S.	HP	Mawmyrsiang	2	2	0			
Investigation	Mechanical	59	Mawmaram D.T.W. W.S.S.	HP	Mawmaram	2	2	0			
Investigation	Mechanical	60	Mawkahir D.T.W. W.S.S.	HP	Mawkahir	2	2	0			
Investigation	Mechanical	61	Dewsaw D.T.W.W.S.S	HP	Dewsaw	1	1	0			
Investigation	Mechanical	62	Krang D.T.W. W.S.S	HP	Krang	4	4	0			
Investigation	Mechanical	63	Umsawmat D.T.W. W.S.S	HP	Umsawmat	2	2	0			

1	2	3	4		6	7	8	9	10	11	12
Investigation	Mechanical	64	Lyngdohphanblang D.T.W.W.S.S.	HP	Lyngdohphanblang	1		1	NF7)damaged by accident	Cannot be made functioned	Alternative piped water supply scheme commissioned
Investigation	Mechanical	65	Ktiehbah D.T.W. W.S.S	HP	Ktiehbah	1	1	0			
Investigation	Mechanical	66	Nongkseh D.T.W. W.S.S.	HP	Nongkseh	2	2	0			
Investigation	Mechanical	67	Lyngkien D.T.W. W.S.S.	HP	Lyngkien	1	1	0			
Investigation	Mechanical	68	Diengiei D.T.W. W.S.S.	HP	Diengiei	1	1	0			
Investigation	Mechanical	69	Manai D.T.W.W.S.S.	HP	Manai	2	2	0			
Investigation	Mechanical	70	Wahlakhew D.T.W. W.S.S.	HP	Wahlakhew	3	3	0			
Investigation	Mechanical	71	Kynsew D.T.W. W.S.S	HP	Kynsew	3	3	0			
Investigation	Mechanical	72	Umthlong D.T.W. W.S.S	HP	Umthlong	2	2	0			
Investigation	Mechanical	73	Mawan D.T.W.W.S.S.	HP	Mawan	1	1	0			
Investigation	Mechanical	74	Mawlieh D.T.W.W.S.S	HP	Mawlieh	4	4	0			
Investigation	Mechanical	75	Pyndem Nongbri D.T.W.W.S.S.	HP	Pyndem Nongbri	1	1	0			
Investigation	Mechanical	76	Umlangrieng D.T.W. W.S.S.	HP	Umlangrieng	1	1	0			
Investigation	Mechanical	77	Wahlangrieng D.T.W. W.S.S.	HP	Wahlangrieng	2	2	0			
Investigation	Mechanical	78	Waitpnor D.T.W.W.S.S.	HP	Waitpnor	4	4	0			
Investigation	Mechanical	79	Mawpat D.T.W.W.S.S.	HP	Mawpat	1	1	0			
Investigation	Mechanical	80	Pyndeng Nongbri dombah D.T.W. W.S.S.	HP	Pyndeng Nongbridohbah	1	0	1	NF3	Cannot be revived	Alternative piped w.s.s commissioned
Investigation	Mechanical	81	Nongkseh D.T.W.W.S.S.	HP	Nongkseh	1	0	1	NF3	Cannot be revived	Alternative piped w.s.s taken up
Investigation	Mechanical	82	Lairtdombah D.T.W. W.S.S.	HP	Lairtdombah	2	2	0			
Investigation	Mechanical	83	Kyrphei D.T.W.W.S.S.	HP	Kyrphei	2	2	0			

1	2	3	4		6	7	8	9	10	11	12
Investigation	Mechanical	84	Umlongmar D.T.W. W.S.S.	HP	Umlongmar	1	1	0			
Investigation	Mechanical	85	Laitmawsing D.T.W. W.S.S.	HP	Laitmawsing	1	1	0			
Investigation	Mechanical	86	Mawsping D.T.W. W.S.S.	HP	Mawsping	1	1	0			
Investigation	Mechanical	87	Lyngkyriem D.T.W. W.S.S.	HP	Lyngkyriem	5	5	0			
Investigation	Mechanical	88	Wahlyngkhar D.T.W. W.S.S.	HP	Wahlyngkhar	1	1	0			
Investigation	Mechanical	89	Ladmyrsiang D.T.W. W.S.S.	HP	Ladmyrsiang	2	2	0			
Investigation	Mechanical	90	Umdoh Mawpud D.T.W. W.S.S.	HP	Umdoh Mawpud	1	1	0			
Investigation	Mechanical	91	Lum-U-Smon D.T.W. W.S.S.	HP	Lum-U-Smon	2	2	0			
Investigation	Mechanical	92	Ichamati D.T.W.W.S.S.	HP	Ichamati	2	2	0			
Investigation	Mechanical	93	Mawmihthied D.T.W. W.S.S.	HP	Mawmihthied	1	1	0			
Investigation	Mechanical	94	Sohrarim D.T.W.W.S.S.	HP	Sohrarim	2	2	0			
Investigation	Mechanical	95	Newcomera D.T.W. W.S.S.	HP	Newcomera	1	1	0			
Investigation	Mechanical	96	Chaklabasti D.T.W. W.S.S.	HP	Chaklabasti	1	1	0			
Investigation	Mechanical	97	Jatap D.T.W. W.S.S.	HP	Jatap	2	2	0			
Investigation	Mechanical	98	Tyllap D.T.W. W.S.S.	HP	Tyllap	2		2	(NF7)damag ed by villages	cannot be revived	Alternative piped w.s.s. commissioned.
Investigation	Mechanical	99	Laitkseh D.T.W.W.S.S.	HP	Laitkseh	2	2	0			
Investigation	Mechanical	100	Kynton-U-Smon D.T.W. W.S.S.	HP	Kynton-U-Smon	1	1	0			
Investigation	Mechanical	101	Umphymai D.T.W. W.S.S.	HP	Umphymai	3	3	0			
Investigation	Mechanical	102	Mawlyndem D.T.W. W.S.S.	HP	Mawlyndem	1	1	0			
Investigation	Mechanical	103	Tynring D.T.W. W.S.S.	HP	Tynring	3	3	0			
Investigation	Mechanical	104	Mawsharoh D.T.W. W.S.S.	HP	Mawsharoh	1	1	0			

1	2	3	4		6	7	8	9	10	11	12
Investigation	Mechanical	105	Mawthumthun D.T.W. W.S.S.	HP	Mawthumthum	1	1	0			
Investigation	Mechanical	106	Mawkhnam D.T.W. W.S.S.	HP	Mawkhnam	2	2	0			
Investigation	Mechanical	107	Umroh D.T.W. W.S.S.	HP	Umroh	2	2	0			
Investigation	Mechanical	108	Nonghali D.T.W.W.S.S	HP	Nonghali	2	2	0			
Investigation	Mechanical	109	Mairang D.T.W.W.S.S.	HP	Mairang	1	1	0			
Investigation	Mechanical	110	Mawding D.T.W.W.S.S	HP	Mawding	1	1	0			
Investigation	Mechanical	111	Mawbsein D.T.W.W.S.S.	HP	Mawbsein	4	4	0			
Investigation	Mechanical	112	Bhoilymbong D.T.W. W.S.S.	HP	Bhoilymbong	1	1	0			
Investigation	Mechanical	113	Mawspung D.T.W. W.S.S.	HP	Mawspung	1	1	0			
Investigation	Mechanical	114	Kdonghulu D.T.W. W.S.S.	HP	Kdonghulu	1	1	0			
Investigation	Mechanical	115	Phlang-u-Diak D.T.W. W.S.S.	STC	Phlang-U-Diak	1	1	0			
Investigation	Mechanical	116	Pyrjat W.S.S.	STC	Pyrjat	1	1	0			
Investigation	Mechanical	117	Mawlieh W.S.S.	STC	Mawlieh	1	1	0			
Investigation	Mechanical	118	Laitkyrsew W.S.S.	STC	Laitkyrsew	1	1	0			
Investigation	Mechanical	119	Diengiong W.S.S.	STC	Diengiong	1	1	0			
Investigation	Mechanical	120	Mawblah W.S.S.	RWH	Mawblah	85	0	85	NF7(villagers are not maintaining the individual structures)	Cannot be made functional	Alternative scheme submitted.Sanctioned awaited.
Investigation	Mechanical	121	Mynsang D.T.W.W.S.S	HP	Mynsang	2	2	0			
Investigation	Mechanical	122	Umrynjah -I WSS	HP	Umrynjah I	1	1	0			
Investigation	Mechanical	123	Umrynjah -I I WSS	HP	Umrynjah II	1	1	0			
Investigation	Mechanical	124	Itshyrwat -II WSS	HP	Itshyrwat II	1	1	0			
Investigation	Mechanical	125	Mawpun II WSS	HP	Mawpun II	1	1	0			
Investigation	Mechanical	126	Manarain I WSS	HP	Manarain I	1	1	0			
Investigation	Mechanical	127	Manarian II WSS	HP	Manarian II	1	1	0			
Investigation	Mechanical	128	Manarian III WSS	HP	Manarian III	1	1	0			
Investigation	Mechanical	129	Manarian IV WSS	HP	Manarian IV	1	1	0			

1	2	3	4		6	7	8	9	10	11	12
Investigation	Mechanical	130	Mawlong I WSS	HP	Mawlong I	1	1	0			
Investigation	Mechanical	131	Mawlong II WSS	HP	Mawlong II	1	1	0			
Investigation	Mechanical	132	Mawlong III WSS	HP	Mawlong III	1	1	0			
Investigation	Mechanical	133	Mawlong IV WSS	HP	Mawlong IV	1	1	0			
Investigation	Mechanical	134	Mawlong V WSS	HP	Mawlong V	1	1	0			
Investigation	Mechanical	135	Mawlong VI WSS	HP	Mawlong VI	1	1	0			
Investigation	Mechanical	136	Lumthlong I WSS	HP	Lumthlong I	1	1	0			
Investigation	Mechanical	137	Lyngkien WSS	STC	Lyngkien	1	1	0			
Investigation	Mechanical	138	Mawtawar WSS	STC	Mawtawar	1	1	0			
Investigation	Mechanical	139	Nongmadan Nongpathaw	STC	Nongmadan	1	1	0			
Investigation	Mechanical	140	Mawklot WSS	STC	Mawklot	1	1	0			
			Sd/ S.Lyngdoh		Sd/ G.P.Dutta						
			SDO(PHE)		SDO(PHE)						
			Spl.Inv Sub Division		Mechanical Sub Division						
			Shillong		Shillong						
			Sd/ D.D.umdor		Sd/ K.D.Talukdar			Sd/ V.K.War			
			SDO(PHE)		EE(PHE)			SE(PHE)			
			Spl.Inv Sub Division		Investigation Division			GS Circle			
			Pynursla		Shillong			Shillong			