

TOTAL NUMBERS OF NON FUNCTIONING PIPED WATER SUPPLY SCHEMES AS ON 31.03.2006

Sl	District	Zone	Division	Due to Theft of pump/motor/transformer/pipes	Due to Old Age of the Scheme	Intra/Inter Village rivalry/dispute over sharing of water sources/land disputes/Damage by miscreants	Drying up of sources./ Change of River course	Collapse of DTW bores/Breakdown of Pumps	Due to flood damage / heavy rain	Due to coal mining, quality problem	Damage due to wild animals	Other reasons	Total number of non functioning schemes
1	2	3	4	5	6	7	8	9	10	11	12	13	14
1	East Khasi Hills	Khasi Hills	GSWS Divn No -I									3	3
2	East Khasi Hills	Khasi Hills	GSWS Divn No -II										0
3	East Khasi Hills	Khasi Hills	Electrical Mawphlang									2	2
4	East Khasi Hills	Khasi Hills	Investigation			1	1					1	3
5	East Khasi Hills	Khasi Hills	Hills			4	1						5
6	East Khasi Hills	Khasi Hills	S&D			1							1
7	East Khasi Hills	Khasi Hills	Sohra	10	1		1						12
8	West Khasi Hills	Khasi Hills	Nongstoin	28	10		2				1	1	42
9	West Khasi Hills	Khasi Hills	Mawkyrwat	21		2	3		2			14	42
Khasi Hills Total				59	11	8	8	0	2	0	1	21	110
10	Ri Bhoi	Ri Bhoi	Nongpoh					1				9	10
11	Jaintia Hills	Jaintia Hills	Electrical Shillong	0								0	0
12	Jaintia Hills	Jaintia Hills	Jowai	3	2	2	8			2			17
Jaintia Hills Total				3	2	2	8	0	0	2	0	0	17
13	East Garo Hills	Garo Hills	Resubelpara			3							3
14	East Garo Hills	Garo Hills	Simsanggiri			1							1
15	South Garo Hills	Garo Hills	Baghmara	3	2	1	2						8
16	West Garo Hills	Garo Hills	Tura		1								1
17	West Garo Hills	Garo Hills	Tura North	14	2		1	7					24
Garo Hills Total				17	5	5	3	7	0	0	0	0	37
Grand Total				79	18	15	19	8	2	2	1	30	174
Percentage				45.40%	10.34%	8.62%	10.92%	4.60%	1.15%	1.15%	0.57%	17.24%	100.00%